REVISION Section review

DISTRIBUTION STANDARD PNM

Types of Hazardous Areas

1. Locations in which ignitable concentration of flammable gases or vapors exist. These locations may include but are not limited to portions of the following:

Tank Farms Oil Refineries Paint Factories Gas Producing Plants Fertilizer Plants

2. Locations in which combustible dust is in the air in quantities sufficient to produce explosive or ignitable mixtures. These locations may include, but are not limited to portions of the following:

Grain Processing or Storing Areas Hay Processing Areas Plant Producing Magnesium or Aluminum Dust Coal Handling Facilities

3. Locations in which easily ignitable fibers or materials producing combustible flying is handled, manufactured, or used. These locations may include, but are not limited to portions of the following:

Rayon, Cotton, or Other Textile Mills Cotton Gin or Cotton - Seed Mills Sawmills Lumberyards

NOTE: If any doubt exists about a particular location, contact the Division Engineer.

Reference: NESC, Article 500 NESC, Rule 127

PNM Policy for Hazardous Areas

Engineering shall design the service. Area lighting shall not be provided by PNM.

Services or Hazardous Areas

DS-13-8.0

11/01/05 E