



NOTES

(1) Can be in conduit or direct buried. For direct buried, use 2" plastic bushing 5975-259796.

REFERENCES

- (1) See DS-18-22.0 Universal Support Bracket
- (2) See DS-18-20.0 Ground Assembly

Material List

Item	Quan.	Description	Stcok #
A	1	100 Amp 240V Contactor	5945-244001
B	1	105-305V Long Life Photo Control	0100-006641
C	4	5/8" x ___ Machine Bolt	DS-18-25.0
D	4	2 1/4" Square Washer	5310-153571
E	4	5/8" MF Locknut	5310-153506
F	7'	#4 Stranded Copper	6145-002298
G	1	Weatherhead	5975-263277
H		2" Rigid Conduit	5975-257857
J	2	Standoff Bracket	5975-260471
K	2	2" Pipe Strap Kit	5975-258145
L	1	2" 90° Galvanized Elbow	5975-259549
M	1	2" Galvanized Coupling	5975-272252
N	1	2" Female Adaptor	5975-263590
P	2	Lag Screw	5305-147794
Q	3	___ Line Tap	DS-18-99.0